



【 ASSEMBLE TOOL 】

- Jig for soldering center and outer conductor:
MMCX(AR)-P-SF/SO-MD2
○Jig for press fitting of cap:
MMCX(AR)-LP-SF047/CV-MD2



【 USAGE PRECAUTIONS OF MMCX(AR) 】

1. Insertion or extraction a plug of MMCX(AR) as perpendicularly as possible with aligning the plug with a receptacle. When aligned insertion or extraction is not performed, it would damage or deform an outer conductor part.
2. Do not apply excess load on soldered section with cable



3	PHOSPHOR BRONZE	GOLD PLATING							
2	PTFE			5	BRASS	NICKEL PLATING			
1	BRASS	GOLD PLATING		4	BERYLLIUM COPPER	GOLD PLATING			
NO.	MATERIAL	FINISH .	REMARKS	NO.	MATERIAL	FINISH .	REMARKS		
UNITS mm		SCALE 5 : 1	COUNT 	DESCRIPTION OF REVISIONS			DESIGNED	CHECKED	DATE
HIROSE ELECTRIC CO., LTD.		APPROVED	·KY. SHIMIZU	16. 07. 25	DRAWING NO.	EDC-363419-00-00			
		CHECKED	·KY. SHIMIZU	16. 07. 25	PART NO.	MMCX(AR)-LP-SF047			
		DESIGNED	·TM. YOSHIDA	16. 07. 25	CODE NO.	CL339-0029-0-00			
		DRAWN	·TM. YOSHIDA	16. 07. 25					