





Usage precautions of MMCX(AR)

Insertion or extraction a plug of MMCX(CAR) as perpendicularly as possible with aligning the plug with a receptacle.
When aligned insertion or extraction is not performed, it would damage or deform an outer conductor part.



RoHS COMPLIANT

4	PHOSPHOR BRONZE	GOLD PLATING			
3	PTFE		7	POLYOLEFIN	HEAT SHRINK TUBING(BLACK)
2	BRASS	GOLD PLATING	6	BRASS	GOLD PLATING
1	BRASS	GOLD PLATING	5	BERYLLIUM COPPER	GOLD PLATING
NO.	MATERIAL	FINISH . REMARKS	NO.	MATERIAL	FINISH . REMARKS

UNITS mm		SCALE 10 : 1		COUNT	DESCRIPTION OF REVISIONS	DESIGNED	CHECKED	DATE
HIROSE ELECTRIC CO., LTD.		APPROVED	TO. KATAYAMA	17. 09. 08	DRAWING NO.	EDC-329687-00-00		
		CHECKED	TO. KATAYAMA	17. 09. 08	PART NO.	MMCX(CAR)-LP-066		
		DESIGNED	NK. OOSAWA	17. 09. 08	CODE NO.	CL339-0031-8-00		
		DRAWN	NK. OOSAWA	17. 09. 08				