


Sep.1.2024 Copyright 2024 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.



- NOTE 1. Connector rotation angle is within ± 45 degree from the above image.
2 Do not apply any excessive stress to the cable assembly position.
3 Lock nuts and tooth washers and O-rings are attached separately in other package.

2	MMCX-LP-088(40)	CL339-0020-1-40			
1	HRM-200-088WBPJBN	CL323-0920-7	3	RF-MF50141 (Black)	NISSEI ELECTRIC CO., LTD.
NO.	PART NO.	CODE NO.	NO.	PART NO.	MANUFACTURER
UNITS mm		SCALE FREE	COUNT 	DESCRIPTION OF REVISIONS	DESIGNED CHECKED DATE
HIROSE ELECTRIC CO., LTD.			APPROVED : TS. NAKAGAWA 20220926	DRAWING NO. EDC-395546-02-00	
			CHECKED : NK. NINOMIYA 20220926	PART NO. HWBPJ-MMCXLP088N2T-A100	
			DESIGNED : MK. INOUE 20220926	CODE NO. CL0321-4275-0-02	
			DRAWN : MK. INOUE 20220926		